



Appendix B

Site Photographs



PHOTOGRAPHIC RECORD

Project: Detailed Site Investigation – 46-58 Marlborough Street, Balaclava, Victoria

Reference: 991.4

Prepared by: RM

Date: 23 May 2020

Reviewed by: ALG



Photo ID: 1 – Drilling works being conducted in the north east of the site

Date: 19/05/2020




Photo ID: 2 – Drilling works being conducted in the south west of the site

Date: 19/05/2020

Project: Detailed Site Investigation – 46-58 Marlborough Street, Balaclava, Victoria

Reference: 991.4

Prepared by: RM

Date: 23 May 2020

Reviewed by: ALG



Photo ID: 3 – Soil exacted from SB08

Date: 19/05/2020



Photo ID: 4 – View of sampling location SB10

Date: 19/05/2020

Project: Detailed Site Investigation – 46-58 Marlborough Street, Balaclava, Victoria

Reference: 991.4

Prepared by: RM

Date: 23 May 2020

Reviewed by: ALG



Photo ID: 5 – Example of 200mm diameter pit within fill material (SB06)

Date: 20/05/2020



Photo ID: 6 – Example of soil inspection for fibrous material within fill (SB05)

Date: 20/05/2020

Project: Detailed Site Investigation – 46-58 Marlborough Street, Balaclava, Victoria

Reference: 991.4

Prepared by: RM

Date: 23 May 2020

Reviewed by: ALG



Photo ID: 7 – Reinstated concrete in car park (SB07).

Date: 26/05/2020



Photo ID: 8 – Reinstated concrete in car park (SB05).

Date: 20/05/2020

Project: Detailed Site Investigation – 46-58 Marlborough Street, Balaclava, Victoria

Reference: 991.4

Prepared by: RM

Date: 23 May 2020

Reviewed by: ALG



Photo ID: 9 – Groundwater low flow monitoring set up at GW02.

Date: 26/05/2020



Photo ID: 10 – Example of installed groundwater monitoring bore (GW03).

Date: 26/05/2020